

The Flash Light item can be recharged via USB cable.

Simply connect it to your computer or with an adaptor to the mains socket (available separately # L719).

The charging time is about 15 minutes.

During charging, a red light is illuminated.

When charging is completed, the light turns off.

We recommend recharging the light unit after each walk and not letting the battery run completely dry.

The intensity of continuous light will decrease after approx. 2.5 hours.

Please only use chargers with a maximum voltage of 5 voltg.

Only charge the battery in the presence of an adult.

Please keep this information.

For optimal safety please use additional high-visibility equipment like a safety vest.

How to shorten the Flash Light Band USB.

Open one side of the light band.

Shorten the band to the desired length simply by cutting it.